

DOCKET NO.: 267135US26X PCT

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

IN RE APPLICATION OF: Eiichi YASUDA, et al.

PATENT NO.: 7,731,294

GROUP: 3636

ISSUED: June 8, 2010

EXAMINER: EDELL, JOSEPH F.

FOR: SEAT

**REQUEST FOR CERTIFICATE OF CORRECTION**

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE  
ALEXANDRIA, VA 22313-1450

SIR:


The following is a Request for Certificate of Correction in Serial Number 10/526,432, now U.S. Patent Number 7,731,294.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,  
MAIER & NEUSTADT, L.L.P.



---

Steven P. Weihrauch  
Registration No. 32,829

Customer Number

**22850**

Tel. (703) 413-3000  
Fax. (703) 413-2220  
(OSMMN 07/09)

Jacob A. Doughty

Registration No. 46,671

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,731,294  
DATED: June 8, 2010  
INVENTOR(S): Eiichi YASUDA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 38, Line 62, "positions of the lower layer portion in to portions of the" should read  
--positions of the lower layer portion to portions of the--

Mailing address of sender:

OBLON, SPIVAK MCCLELLAND,  
MAIER & NEUSTADT, L.L.P.  
1940 DUKE STREET  
ALEXANDRIA, VIRGINIA 22314  
Tel. (703) 413-3000  
Fax. (703) 413-2220  
(OSMMN 07/09)

Patent No. 7,731,294

No. of add'l copies  
@ .30 per page

